



## **SH103S3 Firmware Release Notes**

---

Firmware Revision 526ABBF0 – April 09, 2014

- *SH103S3/90G*
- *SH103S3/120G*
- *SH103S3/240G*
- *SH103S3/480G*

KINGSTON EXPRESSLY DISCLAIMS ALL SUCH WARRANTIES OF ANY KIND, WHETHER EXPRESS, IMPLIED OR STATUTORY, WITH RESPECT TO THE FIRMWARE AND FIRMWARE UPDATES INCLUDING, WITHOUT LIMITATION, WARRANTIES OR CONDITIONS OF QUALITY, PERFORMANCE, NON-INFRINGEMENT, MERCHANTABILITY, OR FITNESS FOR USE FOR A PARTICULAR PURPOSE.

KINGSTON DOES NOT REPRESENT OR WARRANT THAT THE FIRMWARE OR FIRMWARE UPDATES WILL ALWAYS BE AVAILABLE, ACCESSIBLE, UNINTERRUPTED, TIMELY, SECURE, ACCURATE, COMPLETE OR ERROR-FREE, INCLUDING BUT NOT LIMITED TO THE ACCURACY OR COMPLETENESS OF ANY INFORMATION, TEXT, GRAPHICS, LINKS OR OTHER ITEMS CONTAINED WITHIN THE FIRMWARE.

---

## Firmware Rev. 526ABBF0 (04/09/14)

- Fixed a minor issue related to TRIM command

## Previous Firmware Revisions

<b>525ABBF0</b> (No Release Date)	<ul style="list-style-type: none"><li>• Added firmware update support when ATA password is enabled</li></ul>
<b>521ABBF0</b> (No Release Date)	<ul style="list-style-type: none"><li>• Fixed an issue related to COMRESET after entering slumber state</li></ul>
<b>520ABBF0</b> (No Release Date)	<ul style="list-style-type: none"><li>• Resolved a race condition where a write command during SATA error handling process could cause drive to hang</li><li>• Fixed false incrementing with SMART attribute 174</li></ul>
<b>507KC4</b> (No Release Date)	<ul style="list-style-type: none"><li>• Resolved a unique incorrect value bug affecting SMART attribute 231</li><li>• Improved platform compatibility when using Secure Erase command</li><li>• Enhanced overall system compatibility</li></ul>